Date: 08/07/2013

Vermont Agency of Transportation General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems From 01/01/08 To 12/31/12 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Number Of Untimely Deaths	Direction	Road Group
Route: US-2 Continued VT0040500/09CC0 6674	Colchester	0.59	10/14/2009	14:50	Clear	Unknown, Followed too closely	Rear End	1	0	0	N	SH
VT0040500/090CC 06828	Colchester	0.61	10/21/2009	17:24	Clear	No improper driving, Failed to yield right of way	Left Turn and Thru, Broadside v<	0	0	0	Ν	SH
VT0040500/08CC0 2147	Colchester	0.67	04/09/2008	20:10	Clear	No improper driving	Single Vehicle Crash	0	0	0	W	SH
VT0040500/08CC0 7786	Colchester	0.72	11/03/2008	17:45	Clear	No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	0	W	SH
VT0040500/10CC0 5802	Colchester	0.78	09/06/2010	18:10	Cloudy	No improper driving, Failure to keep in proper lane, Under the influence of medication/drugs/alcohol	Head On	2	2	0	E	SH
VT0040500/08CC0 4855	Colchester	0.79	07/19/2008	11:34	Clear	No improper driving, Inattention	Rear End	0	0	0	W	SH
VT0040500/10CC0 7362	Colchester	0.81	11/13/2010	08:15	Clear	Failure to keep in proper lane	Single Vehicle Crash	0	0	0		SH
VT0040500/10CC0 0514	Colchester	1.01	01/30/2010	03:04	Cloudy	Under the influence of medication/drugs/alcohol	Single Vehicle Crash	0	0	0	W	SH
VT0040500/12CC0 4497	Colchester	1.02	07/05/2012	20:50	Clear	No improper driving	Single Vehicle Crash	0	0	0	W	SH
VT0040500/12CC0 7210	Colchester	1.02	10/18/2012	23:10	Clear	No improper driving	Head On	0	0	0	E	SH
VT0040500/11CC0 0465	Colchester	1.14	01/18/2011	15:54	Cloudy	Driving too fast for conditions	Opp Direction Sideswipe	0	0	0	E	SH
VT0040500/12CC0	Colchester	1.14	07/08/2012	01:15	Clear	No improper driving	Single Vehicle Crash	0	0	0	W	SH
4555 VT0040500/09CC0 3035	Colchester	1.18	05/21/2009	16:15	Clear	Fatigued, asleep	Single Vehicle Crash	1	0	0		SH
VT0040500/09CC0	Colchester	1.38	01/20/2009	09:02	Clear	Driving too fast for conditions, No improper	Head On	2	0	0		SH
0373 VT0040500/09CC0	Colchester	1.38	09/23/2009	19:23	Rain	driving Unknown	Single Vehicle Crash	1	0	0		SH
6211 VT0040500/09CC0	Colchester	1.68	06/11/2009	17:03	Rain	No improper driving, Under the influence of	No Turns, Thru moves only, Broadside ^<	1	0	0		SH
3560 VT0040500/09CC0	Colchester	1.69	05/28/2009	17:46	Rain	medication/drugs/alcohol Inattention	Single Vehicle Crash	0	0	0	W	SH
3204 VT0040600/10MT0	Colchester	1.69	10/03/2010	20:42	Clear	Inattention	Same Direction Sideswipe	0	0	0	E	SH
3790 VT0040500/12CC0	Colchester	1.7	05/01/2012	07:25	Rain	Driving too fast for conditions	Rear End	0	0	0	E	SH
2767 VT0040600/10MT0	Colchester	1.79	04/22/2010	22:23	Clear	No improper driving, Failed to yield right of	Head On	1	0	0	E	SH
1400 VT0040500/10CC0	Colchester	<mark>1.86</mark>	08/09/2010	<mark>07:50</mark>	Clear	way Inattention, No improper driving	Rear End	0	0	0	W	<mark>SH</mark>
5030 VT0040500/12CC0	Colchester	1.91	01/04/2012	17:30	Clear	Failed to yield right of way	Left Turn and Thru, Angle Broadside>v	1	0	0		SH
0074) VT0040600/10MT0	Colchester	<mark>1.92</mark>	02/24/2010	<mark>13:44</mark>	Snow		Other - Explain in Narrative	0	0	0	E	<mark>SH</mark>
0619 VT0040500/10CC0 7374	Colchester	1.92	<mark>(11/13/2010</mark>	21:23	Clear	No improper driving, Failed to yield right of way, Disregarded traffic signs, signals, road markings	Left Turn and Thru, Angle Broadside>v	6	0	0	E	(<mark>SH</mark>)
VT0040500/11CC0 0927	Colchester	<mark>1.92</mark>	<mark>02/09/2011</mark>	<mark>08:50</mark>	Cloudy	No improper driving, Driving too fast for	Rear End	0	0	0	W	<mark>SH</mark>
VT0040500/11CC0	Colchester	1.92	10/01/2011	11:13	Rain	No improper driving, Disregarded traffic	Left Turn and Thru, Broadside v<	0	0	0		SH
6913) VT0040500/11CC0	Colchester	<mark>1.92</mark>	12/10/2011	<mark>16:20</mark>	Clear	signs, signals, road markings Driving too fast for conditions	Rear End	0	0	0	W	<mark>SH</mark>
8528 VT0040500/12CC0 2218	Colchester	<mark>1.92</mark>	04/10/2012	05:19	Cloudy	No improper driving, Failed to yield right of way	Left Turn and Thru, Broadside v<	0	0	0	S	SH

*Crash occurred prior to the last Highway Improvement Project. This data should not be used in a crash analysis. UNK indicates the Mile Marker is Unknown.

Page: 14

Date: 08/07/2013

Vermont Agency of Transportation General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems From 01/01/08 To 12/31/12 General Yearly Summaries Information

*	Reporting Agency/ Number	Town	Mile Marker	Date MM/DD/YY	Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Number Of Untimely Deaths	Direction	Road Group
Route	VT0040500/12CC0	Colchester	<mark>1.92</mark>	10/06/2012	<mark>15:30</mark>	Rain	No improper driving, Disregarded traffic signs, signals, road markings	Right Turn and Thru, Same Direction	0	0	0		SH
	VT0040500/09CC0 0318	Colchester	<mark>1.93</mark>	01/17/2009	07:53	Clear	No improper driving, Inattention, Disregarded traffic signs, signals, road	No Turns, Thru moves only, Broadside ^<	0	0	0	S	SH
	VT0040500/10CC0 0952	Colchester	<mark>1.93</mark>	02/24/2010	<mark>04:56</mark>	Snow	markings Driving too fast for conditions, No improper driving	Rear End	0	0	0	<mark>S</mark>	<mark>SH</mark>
	VT0040500/08CC0 6970	Colchester	<mark>(1.94</mark>	10/03/2008	06:26	Cloudy	No improper driving, Failed to yield right of way, Visibility obstructed	(Head On	0	0	0	E	SH
	VT0040500/09CC0 0119	Colchester	<mark>1.94</mark>	01/07/2009	<mark>13:30</mark>	Cloudy	No improper driving, Inattention	Other - Explain in Narrative	0	0	0		SH
	VT0040500/09CC0 7699	Colchester	1.94	11/29/2009	<mark>19:53</mark>	Clear	No improper driving, Failed to yield right of	Head On	0	0	0	E	SH
	VT0040500/10CC0 2030	Colchester	<mark>1.94</mark>	04/13/2010	<mark>08:50</mark>	Clear	No improper driving, Followed too closely	Rear End	0	0	0	W	SH
	VT0040500/11CC0 5581	Colchester	1.94	08/08/2011	17:04	Clear	No improper driving, Failed to yield right of way	Left Turn and Thru, Angle Broadside>v	0	0	0	E	SH
	VT0040500/11CC0 7091	Colchester	<mark>1.94</mark>	10/10/2011	<mark>16:45</mark>	Clear	Inattention, Unknown	Rear End	2	0	0	W	<mark>SH</mark>
	VT0040500/12CC0 1335	Colchester	1.94	03/07/2012	07:31	Cloudy	Distracted, No improper driving	Rear End	1	0	0	E	SH
	VT0040500/12CC0 3686	Colchester	<mark>1.94</mark>	06/05/2012	<mark>10:28</mark>	Cloudy	Failed to yield right of way, No improper	Same Direction Sideswipe	0	0	0	W	<mark>SH</mark>
	VT0040500/12CC0	Colchester	<mark>(1.94</mark>	06/19/2012	<mark>19:25</mark>	Clear	driving) No improper driving, Inattention	Rear End	0	0	0	W	SH
	4060 VT0040500/10CC0	Colchester	<mark>1.95</mark>	11/10/2010	<mark>07:30</mark>	Cloudy	Inattention, No improper driving	Rear End	0	0	0	W	SH
	7296 VT0040500/12CC0	Colchester	<mark>(1.95</mark>)	03/14/2012	06:55	Clear	No improper driving, Failed to yield right of	Left Turn and Thru, Angle Broadside>v	1	0	0	E	SH
	1495 VT0040500/08CC0	Colchester	<mark>1.96</mark>	03/21/2008	<mark>19:04</mark>	Clear	way No improper driving, Visibility obstructed,	Rear End	0	0	0	E	<mark>SH</mark>
	1747 VT0040500/10CC0	Colchester	2.03	04/12/2010	07:49	Clear	Inattention Followed too closely, No improper driving	Rear End	0	0	0	W	SH
	2006 VT0040500/10CC0	Colchester	<mark>2.03</mark>	12/15/2010	<mark>11:30</mark>	Cloudy	Driving too fast for conditions	Opp Direction Sideswipe	0	0	0		<mark>SH</mark>
	8041 VT0040500/10CC0	Colchester	2.04	01/12/2010	12:54	Cloudy	Driving too fast for conditions, Inattention	Single Vehicle Crash	0	0	0		SH
	0215 VT0040500/12CC0	Colchester	2.04	01/23/2012	<mark>16:30</mark>	Rain	Driving too fast for conditions, Failed to	Other - Explain in Narrative	0	0	0	W	SH
	0456 VT0040600/12MT0	Colchester	2.04	10/05/2012	18:47	Clear	yield right of way No improper driving, Inattention	Rear-to-rear	1	0	0		SH
	4102 VT0040500/08CC0	Colchester	2.05	05/15/2008	15:51	Clear	No improper driving, Distracted	No Turns, Thru moves only, Broadside ^ <	0	0	0		SH
	3023 VT0040500/09CC0	Colchester	2.05	05/15/2009	14:00	Clear	Inattention, Driving too fast for conditions,	Rear End	1	0	0	W	SH
	2839 VT0040500/10CC0	Colchester	2.05	02/06/2010	<mark>13:30</mark>	Clear	No improper driving No improper driving, Followed too closely	Rear End	2	0	0	W	SH
	0641 VT0040500/09CC0	Colchester	2.09	12/23/2009	06:42	Snow	(Failure to keep in proper lane, No improper	Opp Direction Sideswipe	0	0	0	E	SH
	8192 VT0040500/10CC0	Colchester	2.1	12/06/2010	17:30	Snow	driving Driving too fast for conditions, No improper	Rear End	0	0	0	E	SH
	7877 VT0040500/12CC0	Colchester	2.1	03/01/2012	18:50	Snow	driving Other improper action, No improper driving	Other - Explain in Narrative	0	0	0		SH
	1249 VT0040500/12CC0	Colchester	2.1	04/11/2012	21:06	Clear	No improper driving, Inattention	Left Turn and Thru, Broadside v<	1	0	0	S	SH
	2261 VT0040500/12CC0	Colchester	2.1	07/27/2012	14:34	Clear	No improper driving, Disregarded traffic	Left Turn and Thru, Broadside v<	1	0	0	_	SH
	5069						signs, signals, road markings, Inattention						

*Crash occurred prior to the last Highway Improvement Project. This data should not be used in a crash analysis. UNK indicates the Mile Marker is Unknown.

Page: 15

Date: 08/07/2013

Vermont Agency of Transportation General Yearly Summaries - Crash Listing: State Highways and All Federal Aid Highway Systems From 01/01/08 To 12/31/12 General Yearly Summaries Information

Reporting Agency/ * Number	Town	Mile Marker		Time	Weather	Contributing Circumstances	Direction Of Collision	Number Of Injuries	Number Of Fatalities	Number Of Untimely Deaths	Direction	Road Group
Route: US-2 Continued VT0040500/08CC0 2992	Colchester	2.11	05/04/2008	17:51	Clear	Unknown	Rear End	0	0	0	S	SH
(VT0040500/08CC0) (5247)	Colchester	2.11	08/02/2008	17:10	Cloudy	Followed too closely, Swerving or avoiding due to wind, slippery surface, vehicle, object, non-motorist in roadway etc, No improper driving	(Rear End	0	0	0	S	SH
VT0040500/10CC0 2447	Colchester	2.11	04/28/2010	05:54	Snow	No improper driving, Visibility obstructed	Rear End	0	0	0	W	SH
VT0040500/10CC0 7962	Colchester	2.11	12/11/2010	17:28	Clear	No improper driving, Disregarded traffic signs, signals, road markings	No Turns, Thru moves only, Broadside ^<	0	0	0	S	SH
VT0040500/12CC0	Colchester	2.11	10/06/2012	<mark>11:04</mark>	Rain	Driving too fast for conditions	Opp Direction Sideswipe	0	0	0	E	SH
6889 VT0040500/09DMV	Colchester	2.12	01/07/2009	06:17	Snow	No improper driving	Left Turn and Thru, Angle Broadside>v	0	0	0	E	SH
0005 VT0040500/09CC0 0602	Colchester	<mark>2.12</mark>	01/30/2009	18:53	Cloudy	No improper driving, Failed to yield right of way, Disregarded traffic signs, signals, road markings	Left Turn and Thru, Angle Broadside>v	0	0	0	E	SH
VT0040500/09CC0 8283	Colchester	2.13	12/28/2009	14:54	Snow	Driving too fast for conditions, Wrong side or wrong way, No improper driving	(Head On	0	0	0	E	SH
VT0040600/11MT0 4299	Colchester	<mark>2.13</mark>	10/24/2011	<mark>16:16</mark>	Clear	or wrong way, no improper unving	Left Turn and Thru, Same Direction Sideswipe/Angle Crash vv	0	0	0		SH
VT0040500/12CC0 1298	Colchester	2.18	03/05/2012	08:10	Clear	No improper driving, Driving too fast for conditions	Rear End	0	0	0	E	SH
VT0040500/08CC0 3981	Colchester	2.19	06/05/2008	14:25	Clear	Inattention, No improper driving	Rear End	0	0	0	N	SH
VT0040500/10CC0	Colchester	2.19	08/02/2010	16:15	Clear	No improper driving, Driving too fast for	Rear End	0	0	0	E	SH
4853 VT0040500/10CC0	Colchester	2.19	08/16/2010	18:31	Clear	conditions, Inattention No improper driving, Visibility obstructed	Same Direction Sideswipe	0	0	0	E	SH
5243 VT0040500/11CC0	Colchester	2.19	03/15/2011	07:56	Clear	No improper driving, Inattention, Followed	Rear End	0	0	0	E	SH
1679 VT0040500/11CC0	Colchester	2.19	03/18/2011	19:50	Clear	too closely Inattention	Rear End	0	0	0	E	SH
1780 VT0040500/11CC0	Colchester	2.19	06/15/2011	19:01	Cloudy		Rear End	0	0	0	E	SH
4050 VT0040500/11CC0	Colchester	2.19	07/16/2011	18:26	Clear	Inattention, No improper driving	Rear End	0	0	0	E	SH
4946 VT0040500/11CC0	Colchester	2.19	11/23/2011	16:41	Snow	Driving too fast for conditions	Single Vehicle Crash	0	0	0	S	SH
8032 VT0040500/11CC0	Colchester	UNK	02/03/2011	07:57	Unknown	No improper driving, Inattention	Rear End	0	0	0	S	SH
0849 VT0040500/11CC0	Colchester	UNK	11/20/2011	11:08	Rain	No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	0	E	SH
7985 VT0040100/20082	Burlington	0	02/10/2008	12:27	Snow	No improper driving	Rear End	0	0	0	W	SH
659 VT0040100/20082	Burlington	0	02/12/2008	07:52	Not Reported	Inattention, Visibility obstructed, No	Right Turn and Thru, Broadside ^	0	0	0	N	SH
773 VT0040100/08088	Burlington	0	05/07/2008	14:37	Clear	improper driving Failed to yield right of way, Inattention, No	Same Direction Sideswipe	0	0	0	W	SH
89 VT0040100/08107	Burlington	0	05/29/2008	00:44	Clear	improper driving Unknown, No improper driving	Rear End	0	0	0		SH
73 VT0040100/08-	Burlington	0	06/21/2008	09:46	Clear	No improper driving	Rear End	0	0	0	W	SH
12893 VT0040100/08-	Burlington	0	06/29/2008	17:30	Cloudy	Inattention, No improper driving	No Turns, Thru moves only, Broadside ^<	0	0	0		SH
13706 VT0040100/08-	Burlington		07/16/2008	14:35	Clear	Inattention	No Turns, Thru moves only, Broadside ^<	0	0	0	N	SH
15324	Laningron	0	51710/2000	14.00	0.001			0	0	0		

*Crash occurred prior to the last Highway Improvement Project. This data should not be used in a crash analysis. UNK indicates the Mile Marker is Unknown.