

Relevant Water Quality Projects – Franklin County Natural Resources Conservation District
Basin 5 BWQC – 4/20/22



Willow fascine trenches being dug in floodplain along river

Relevant Water Quality Projects – Franklin County Natural Resources Conservation District
Basin 5 BWQC – 4/20/22



Willow fascine in trench being buried

Relevant Water Quality Projects – Franklin County Natural Resources Conservation District
Basin 5 BWQC – 4/20/22



Willow fencing in valley on agricultural lands

Relevant Water Quality Projects – Franklin County Natural Resources Conservation District
Basin 5 BWQC – 4/20/22



Bridge removal and access road removal design for removal of stream encroachment

Relevant Water Quality Projects – Franklin County Natural Resources Conservation District
Basin 5 BWQC – 4/20/22



Stream Stabilization Project on a Farm by Canadian Border

Relevant Water Quality Projects – Franklin County Natural Resources Conservation District
Basin 5 BWQC – 4/20/22



Dam Removal + Scoping + Monitoring